



MANUFACTURING, INC.

EZ Hauler 3500/3800 Product Announcement

Subject: Outrigger Gusset Update

Date: June 8, 2006

To: EZ Hauler 3500/3800 Owners


Announcement: CCG1651

From: SDP Product Support

Phone: 765-768-5000

EZ Hauler models 3500/3800 manufactured prior to June 1, 2006 may experience hydraulic outrigger structural damage when overloaded. Failure to update could result in total outrigger failure!

This mandatory update includes that gussets be welded in the backs of the outrigger body mounting plates on both the front and back of the unit. If you do not have this update, then you must call SDP Manufacturing, Inc., then they will supply you with the materials needed. The gussets will need welded in, so a qualified welder must do this work.



SDP Manufacturing, Inc.

400 Industrial Drive

Dunkirk, IN 47336

Tel: 765-768-5000 Fax: 765-768-5015

Announcement #: CCG1651

Print Date: 6/8/2006